DCH Windows POS Scanner Setup

1 Set All Defaults

2 Begin New Rule

3 Send All Data That Remains

4 Send Enter Key (Scan Three Times)

5 Send 1

6 Send Enter Key

7 Send ~

8 Save Rule

9 Quit Entering Rules

10 Convert UPC-E1 to UPC-A
(Enable)

**11** Convert UPC-E to UPC-A
(Enable)

12 System Character & Country Code
(<COUNTRY CODE> <SYSTEM CHARACTER> <DATA>)